


**ANNUAL COMPREHENSIVE SAFETY INSPECTION REPORT
STATE BOARD OF EDUCATION
ADMINISTRATIVE RULE - SREF 2014 & F.A.C. 69A-58
FISCAL YEAR 2022-2023**

College Facility: St. Petersburg College FIRE DISTRICT: Clearwater
 SCHOOL / FACILITY: Clearwater Campus
 ADDRESS: 2465 Drew St. Clearwater FL

OF SERIOUS FIRE SAFETY VIOLATIONS 0

OF NON-SERIOUS FIRE SAFETY VIOLATIONS 2

FIRE DISTRICT FIRE SAFETY INSPECTOR NAME PRINTED (IF JOINT INSPECTION)		Jeb W. Bynum (Municipal Fire Safety Inspector)	November 14, 2022
		COLLEGE BOARD FIRESAFETY INSPECTOR NAME PRINTED	INSPECTION DATE
FIRE DISTRICT FIRE SAFETY INSPECTOR SIGNATURE (IF JOINT INSPECTION)		Fire Prevention Specialists, Inc., 609 Gina Lane, Melbourne, FL 32940 321-302-3993	
		INSPECTOR ADDRESS & PHONE NUMBER	
SIGNATURE DATE	FIRE INSPECTOR CERTIFICATION NUMBER	 11/22/22	133209
		COLLEGE BOARD FIRE SAFETY INSPECTOR SIGNATURE / DATE	FIRE INSPECTOR CERTIFICATION NUMBER

LOCATION:

Deficiency locations will be identified by a building number followed by the room number (e.g. 2-505 or 1-133A). These numbers are usually affixed above the door leading into that particular room. Or if the deficiency in an area other than an identifiable room number, the area in question will be specifically identified. For example: Pressbox, Field House, Pavillion, etc.

St. Petersburg College has met the requirements of F.S.S. 1013.12(2)(d): YES ___ NO

Approval of Reports by Board (Including Letter) ___ YES ___ NO

THE UNDERSIGNED ATTESTS TO THE REVIEW OF THIS REPORT IN ITS ENTIRETY AND ACKNOWLEDGES AWARENESS OF THE DISCOVERED DEFICIENCIES.

FACILITY ADMINISTRATOR NAME PRINTED

FACILITY ADMINISTRATOR SIGNATURE

FACILITY ADMINISTRATOR TITLE

SIGNATURE DATE

